

If the problem exists in the frequency converter, why not write the AD against that part instead of the aircraft? Frequency converters are used on many aircraft and the problem may exist elsewhere as well. Just reading Boeing service bulletins may be too myopic an approach to the problem.

Why not list the defective part by manufacturer and part number? Listing this way may allow detection of similar problems on other aircraft and possible PMA alternative units.